

✕	✕	✕	✕
heat sink drilling/tapping template			
drill/tap all 8 locations for 4-40 machine screws or your metric equivalent. heat sink should weigh 6 pounds and have a .375 base under the fins			
✕	input side	✕	✕
✕	output side	✕	✕